

Existing Conditions:



Location of windows to be replaced. Note: this picture taken prior to window restoration



After window restoration. New windows to match style and color or restored windows

Location of windows to be replaced



State House

Pinckney St

Brimmer St

Charles St

Cedar Ln Way

Mt Vernon St

Mt Vernon St

Joy St

Monorial Shell

Storrow Dr

The Paramount

Lime St

Branch St

63 Beacon Street

Beacon St

Chestnut St

Cheers

Byron St

Beacon St

Make Way for Ducklings

Boston Common
Visitors Center

Boston
Common

Public Alley 421



Close-up of window to be replaced

Relocate hose bib to granite and replace with brass hose bib




Close-up of other window to be replaced



Basement window on adjacent property (162 Beacon?). Proposed black iron security grille to match this on both of our new windows.


Additional Information Requested
Existing Conditions (Interior photos):





1 WINDOW 1 ELEVATION (2 UNITS)
Scale: 3" = 1'-0"

RADIUS SILL TO FOLLOW
STONE SILL



2 Section
Scale: 3" = 1'-0"


All profiles and trim to match restored windows above. Historic glass will be used to match windows above. Paint to match windows above.

JACKSON SCHILLACI FINE WOODWORKING + TURNING	
PROJECT: King's Chapel, 64 Beacon Street CONTRACTOR: Cleary & Son DATE: 7.25.18	
REVISIONS	
APPROVED BY: _____	
DATE: _____	
DWG #	
SH-1	

63 BEACON ST. - IRON SECURITY GRATES

$1/8'' = 1''$

5/8'' ROUND BAR, 3'' O.C. TYP.



* ALL METAL HOT DIPPED GALVANIZED & PAINTED BLACK

Design for security gates (this photo from adjacent property):



Proposed hose bib location on joint intersection

