
BACK BAY ARCHITECTURAL COMMISSION HEARING MARCH 9, 2022 397-399 COMMONWEALTH AVE H+A WWW.HACIN.COM @HACINASSOCIATES









Existing Conditions – Commonwealth Facade









Existing Conditions – Marlborough Street Facades

397-399 COMMONWEALTH AVE



Marlborough Street South Side



Marlborough Street North Side

Marlborough Street Block Context Photos

397-399 COMMONWEALTH AVE

H+/









Typical Adjacent Facades on South Side of Marlborough




South side of Marlborough from the East towards Charlesgate













Marlborough Street Materials + Expression


397-399 COMMONWEALTH AVE

H+











Marlborough Street Materials + Expression



MARLBOROUGH STREET







MARLBOROUGH STREET PARKING+DRIVE, BRICK PAVING REPLANT FLOWERING BUSHES LEVEL 1 TERRACE LEVEL 5 TERRACE LEVEL 2 TERRACE MECHANICAL ZONES, CONCEALED FROM STREET VIEW, NO MECHANICAL ON TOP ROOF 401 LEVEL 6 ROOF LEVEL 6 TERRACE FRONT YARD, GROUND COVER, LOW PLANTING AT BUILDING, SMALL TREES IN YARD NEW GRANITE WALK TO EXISTING STAIRS **COMMONWEALTH AVENUE**

Site + Roof Plan - Proposed



Proposed Floor Plans



Marlborough Street South Side



Marlborough Street North Side

Marlborough Street Block Context Photos 397-399 COMMONWEALTH AVE



Marlborough Street South Side



Marlborough Street North Side

Proposed Design

397-399 COMMONWEALTH AVE

H+<u></u>

What we heard...

This is a background building, goal should be a quiet facade with nice details including windows

Bowfront articultion makes sense in this context

Height feels too low for infilling the block, consider tall parapet

Windows are important, sould consider inspiration from neighboring buildings

Studio window at recessed facade feels prominent

Landscape should receive attention









Proposed Design Marlborough Street







Existing and Proposed Views - Marlborough Street







Existing and Proposed Views - Marlborough Street



Proposed Views - Marlborough Street

397-399 COMMONWEALTH AVE

H+<u></u>




Marlborough Street looking East




Marlborough Street looking West

Proposed Views















Brick Options




Cast Stone





Pre-patinated Copper







Ornamental Metal Rails


New Construction Materials







LEVEL 1 TERRACE



EXISTING GAS LAMP

TING BRICK WALL WITH BROWNSTONE CAP

3 BRICK PARKING SPACES

3 & PERENNIAL PLANTING

CURB & SHRUB PLANTING

Landscape Concept 397-399 COMMONWEALTH AVE

EXISTING GAS LAMP

REPLACED IN KIND

LOW GRANITE WALL END

TRENCH DRAIN

CONCRETE PAVING

SHRUB PLANTING, TYP.

EXISTING BRICK SIDEWALK TO BE

NEW BRICK WALL WITH GRANITE CAP


EXISTING BRICK WALL WITH

BRICKRAMP DOWN TO GARAGE














Landscape Concept
397-399 COMMONWEALTH AVE










Existing elevator head house, galvanized corrugated and standing seam




Existing visible elevator head house (to be removed)



View across Commonwealth Avenue





Sight Line Section Analysis






View across Marlborough Avenue





Sight Line Section Analysis





397 Commonwealth Avenue is a 5 story building constructed in 1924 as a dormitory and was used over time for various purposes. It will be renovated and expanded to the rear and vertically for a 6th story addition. The remodel will conform to the zoning height limit of 65 feet and floor area ratio limit of 3.0

The proposed use will be multifamily condominiums with 6 for-sale units. The basement will include one unit at the front of the building, condominium owner storage spaces, building utilities and parking for up to 8 cars. Level 1 will include the building lobby and one living unit, levels 2-4 will each be full floor units and level 5-6 will be a two story penthouse unit.

The front façade will be restored with wood replacement windows to mach the style of the existing replacement windows. The front door, which currently is fixed closed, will be replaced in kind and returned to function as the primary building entrance.

The façade facing Marlborough street will be a new brick and cast stone facade with wood windows and a new garage entrance to the basement level. The 6th floor addition will be set back so it is not visible from Commonwealth Avenue. Its windows will include steel frame studio windows and doors.

Proposed Project Description



2014 Photo from backbayhouses.org

Constructed in 1924-25 on a vacant lot by the William H. Whitcomb Construction Company for the Moorland Company. The architect may have been Hiram Bertrand Andrews, a civil engineer and expert on reinforced concrete. It operated as a residence for young men.

1934 sold and operated as The Moorland lodging house for men.

1936 acquired license to serve alcoholic beverages.

1937 conversion to a 51 room hotel. A catering company also operated in the building.


1958 converted to professional offices in combination with 395 Commonwealth as the Heathstone Building for Heathstone Insurance.

1964 converted to a dormitory and cultural center for women after purchase by the Association for Cultural Interchange.

1971 combined with 395 Commonwealth as a single building.


1988 addition to the rear as part of a chapel accessed from 395 Commonwealth.

One of only twelve Back Bay addresses to have frontage on both Commonwealth Avenue and Marlborough Street.



Back Bay Historic District and Block Plan





Project Site - 397 Commonwealth Avenue

Typical street block

Front yard zone

Double-sided block breaks down

Marlborough Street Analysis and Block Plan





Existing (non-original) casement windows at Level 2, double-hung at Levels 3-5



Existing (non-original) casement windows at Level 1





Existing non-historic wood casements - simulated divided lights, no IGU spacer




Existing non-historic double hung - Pella wood replacement windows with channel balances

Existing Window Photos








True Divided Lite Muntin

Double Hung Window - Proposed

Outswing Casement - Proposed

Proposed Replacement Window Details





Steel Studio Windows (penthouse unit)

Proposed Window Details - Marlborough

