

What we heard...

Openings feel like windows are missing; too much sky visible through them.

Additional height is helpful, but expression does not feel right - consider alternatives.

Landscape plans need to be reviewed in more detail in a subsequent meeting.

Addition height should approxmiate the window sill of the adjacent building's top floor.



March Meeting - Marlborough Street Concept



Proposed Design Marlborough Street

397 COMMONWEALTH AVE





Trellis precedent (84 Beacon)

Existing and Proposed Views - Marlborough Street

397 COMMONWEALTH AVE



Proposed Design Marlborough Street

397 COMMONWEALTH AVE



Proposed Views - Marlborough Street

397 COMMONWEALTH AVE

H+



Marlborough Street looking East





Marlborough Street looking West

Proposed Views


397 COMMONWEALTH AVE











SITE MATERIALS







Granite Pavers

20 FEET

REFER TO ARCHITECTURAL

DRAWINGS FOR ENTRANCES

LANDSCAPE LIGHTING

EXISTING MAGNOLIA

WIDE GRANITE CURB, TYP.

GRANITE PAVERS

END GATE AT ABUTTER'S EXISTING FENCE





PLANTER

LANDSCAPE LIGHTING

SHRUB PLANTING, TYP.

PROPOSED MAGNOLIA

REMOVE & REPLACE CONCRETE SIDEWALK FOR POSITIVE DRAINAGE

397 COMMONWEALTH AVE.

GROUND COVER, TYP.

28"-32" NEW ORNAMENTAL METAL FENCE MEETS ABUTTER'S FENCE

GRANITE BENCH BLUE STONE PAVERS





New Cast Iron Fence to match balcony railings (precedent below)

Evergreen Low Boxwood Hedge

New Magnolia Tree

(To match existing on leff



COMMONWEALTH AVENUE



Low Ambient Landscape Lighting



Replace/Regrade Existing Concrete Sidewalk



397 COMMONWEALTH AVE

