



Proposed location and anchorage of new support bracket, consistent with examples located at 39, 45, 53 and 55 Beacon Street.

Existing bracket, found to be structurally compromised and not historically consistent with other examples in the area.