

SURROUNDING CONTEXT







DESCRIPTION OF PROPOSED WORK


1. Replace existing damaged/broken railings at front stoop. Refer to attached drawings.


FRONT ENTRY RAILING



Damage on existing front railings









Damage on existing front railings


STREET PRECEDENTS




163 WEST NEWTON ST.

116 WEST NEWTON ST.







EXISTING RAILINGS:

Mismatching Broken Corroded Missing Pieces

