


Bank of America, 557 Tremont St


Bank of America would like to update their exterior lighting for safety and security reasons. The following pages reflect the proposed changes.



Bank of America, 557 Tremont St

Lobby Entry


 Remove existing light fixture and replace with fixture pictured Below (Cutsheet SE)

 Add new light fixture to match Below (Cutsheet SE)




Bank of America, 557 Tremont St

Associate Entrance

 Add new light fixture to match Below (Cutsheet SH)



 Add new light fixture to match below (Cutsheet BO)



Flat Lens

