2011-1	(Issued Date	Title	Status	References	References	Commissioner (na
	(mm/dd/yyyy)	1180	(Active,	Other CBs	(MGLs, CMRs, City Code, etc)	Commissioner (in
	(ITIITI/GG/yyyy)		Superseded,	(Rescind/Replace)	(WOLD, OWN to, Only Code, Cto)	
			Rescinded)	(rtescind/rteplace)		
2023-04	11/29/2023	Implementation of An Ordinance Governing Construction and Demolition	Active		CBC 16-65	Sean Lydon
		Operations in the City of Boston				
2023-03	10/4/2023	Fast Track Program	Active	Rescinds CB2003-05	780 CMR 105.11	Sean Lydon
2023-02	7/18/2023	Compliance Documents Required Prior to Issuance of Certificate of Occupancy for Projects Located witin Floodplain Districts	Active		BZC Art. 25	Sean Lydon
2023-01	1/5/2023	Definition and Requirements of an Affidavit Project in the City of Boston	Active	Rescinds CB1997-07		Sean Lydon
2022-02	3/14/2022	Certification of Roof Decks	Active	Rescinds CB2008-01	CBC 9-9.13	Sean Lydon
2022-01	3/8/2022	Further Modified Procedure for Off-Hours Inspections/Assignment ("Details") Reguests: Payment of Fees	Active	Rescinds CB2020-02		Sean Lydon
2021-03	7/1/2021	Establishment of Application Requirements, Administrative Procedures and	Active		CBC 9-9.15	Sean Lydon
		Administrative Regulations regarding the Permitting of Retail Residential			105 CMR 590	
2004.00	E/00/0004	Kitchens pursuant to City of Boston Code, Ordinances Chapter 9-9.15 Modified Construction Site Return-to-Work Protocols	A ('	Rescinds CB2020-01		
2021-02	5/28/2021		Active		MOL - OCOA	Sean Lydon
2021-01	3/26/2021	Re-establishment of the Ethics Committee to assist the Inspectional Services	Active	Rescinds CB 1999-04	MGL c.268A	Dion Irish
		Department and its employees in ensuring strict compliance with G.L. c.268A and G.L. c.268B			MGL c.268B	
2020-03	10/27/2020	Investigation & Enforcement Team (I&E Team) Complaint Investigation and	Active		CB 2005-02	Dion Irish
		Inspection Protocols Relative to COVID-19				
2020-02	7/6/2020	Procedure for Off-Hours Inspections/Assignment ("Details") Requests;	Rescinded byCB2	Rescinds CB2003-03A		Dion Irish
		Payment of Fees		Rescinds Comm. Ltr		
				dated 9/1/2006		
2020-01	5/18/2020	Construction Site Return-to-Work Protocols and Requirements	Rescinded by			Dion Irish
			CB2021-01			
2018-06	12/28/2018	Closure Notice of a Health Permit	Active			William Christopher
2018-05	12/28/2018	Temporary Suspension of a Health Permit (TSOP)	Active		105 CMR 590.014	William Christopher
2018-04	12/27/2018	Short Term Residential Rentals	Active		CBC 9-14	William Christopher
2018-03	10/10/2018	Off Hours Permits	Active		CBC 16-26.4	William Christopher
					CBC 18-2A	
2018-02	5/23/2018	Plastic Bag Ordinance	Active		CBC 17-19.1	William Christopher
2018-01	2/23/2018	Short Form or Minor Alteration Permits	Active			William Christopher
2017-04	12/1/2017	Procedure for Obtaining a Demolition Permit	Active	Rescinds CB 1985-04 Rescinds CB 1985-05		William Christopher
2017-03	8/9/2017	Policies and Procedures for Making Entry to an Occupied Residential Dwelling	Active	Rescinds CB 2010-11	2005 Federal Consent Decree	William Christopher
		for Purposes of an Administrative Inspection				
2017-02	4/21/2017	Establishment of the On-Call Manager List and Standard Rules and Procedures for On-Call Managers	Active	Rescinds CB 2002-03		William Christopher
2017-01	1/25/2017	Construction Site Temporary Informational Signage	Active			William Christopher
2016-06	10/12/2016	Vertical Measurement of Roofs and Height Restrictions	Active			William Christopher
2016-05	9/6/2016	Restaurant Grading System	Active		105 CMR 590	
2016-01	3/4/2016	Energy Storage System Markings for All New Installations over 50 Volts	Active			William Christopher
2015-02	11/30/2015	Calculation of Permit Fees, Definition of Fair Cost of Construction and	Active	Rescinds CB 2012-02		William Christopher
		Application of Penalty Fees				
2011-07	10/21/2011	P&PM - Guidelines for the Enforcement of the Site Cleanliness Ordinance in		Rescinds and replaces		
	0/00/02 : 3	the City of Boston		CB2001-03		
<u>2011-06</u>	9/20/2010	P&PM re: Insurance Claim Loss under MGL c.139, s.3B (see CB 2004-01)				
2011-05	11/4/2011	Transfer of Building Documents to Off Site City Archive Facility		Rescinds and replaces	CBC 9-1	
2011 -		0 (11 + (PPM)		CB 2003-04	MGL c.4, s.7	
<u>2011-04</u>	0/40/0044	Occupancy Committee* (PPM)				
2011-03	8/18/2011	Construction Site Temporary Informational Signage		1		

2011-02	2/10/2011	Inspectional Services Department Hearings		Rescinds and replaces CB 2002-02 CB 2002-02A	MGL c. 30A, s.10 & 11 CBC 9-9 105 CMR 400.500 105 CMR 410.831 105 CMR 850-860	
2011-01	1/23/2011	Effective Date for the Applicability of the "Stretch Energy Code" (8th Edition Building Code, Appendix 115.AA)			8th ed. Building Code, Appendix 115.AA	
2010-11		Rescinded by CB 2017-03	Rescinded by CB			
2010-10	11/8/2010	Required Permitting for All Drilling Operations within the City of Boston		Rescinds and replaces CB 2001-09	780 CMR	
2010-09 2010-08						
	6/10/2010	Definition of "Street": Posten Zening Code Article 2. Section 44 and Article 2A		Possinds and replaces	BZC Art. 2, s.44	
2010-07	6/10/2010	Definition of "Street": Boston Zoning Code Article 2, Section 44 and Article 2A		Rescinds and replaces CB 2000-06	BZC Art. 2A	
2010-06	6/21/2010	Reconstruction of Buildings Under Article 4, Section 4-1 of the Boston Zoning Code		Rescinds and replaces CB 1999-02	BZC Art. 4, s.4-1	
2010-05 2010-04	5/17/2010	City of Boston Regulations for the Implementation of the Security Ordinance for Elderly/Handicapped Housing Developments		Rescinds and replaces CB 1989-01	CBC 9-11	
2010-03	6/24/2010	Rules and Regulations Regarding Free Standing Signs Located on Public vs. Private Property			CBC 16-12.3	
2010-02	2/23/2010	Appeal Process: Vacant and Foreclosed Properties Ordinance			MGL c.143, s.3 780 CMR 122.1	
2010-01	2/10/2010	Establishment of Maximum Allowable Occupant Loads in Places of Assembly (Applicable Only to New Assembly or to Those Seeking an Increase in the Existing Capacity)		Replaces CB 2007-05	780 CMR	
2009-04	12/31/2009	Procedure to Be Followed for the Permitting of Rooftop Agricultural Systems or Roof Gardens				
2009-03	12/31/2009	Administrative Procedure for Answering Requests for Public Documents		Replaces CB 2000-04	MGL c.66, s.10	
2009-02	11/1/2009	Procedures for the Writing and Issuance of All Violations for Payphone Istallation			Zoning Code*	
2009-01	12/31/2009	Procedures for Issuing Citations for Vacant and/or Foreclosed Properties			CBC 16-52	
2008-03	12/1/2008	8/17/2011		Rescinds and replaces CB 2005-03		
2008-02	5/19/2008	Subdivisions		Rescinds 1998-01		
2008-01	3/5/2008	Certification of Roof Decks	Rescinded byCB2	022-02	CBC 9-9.13	
2007-02	10/5/2007	Demolition (Take Down) Permits				
2007-01	6/1/2007	Construction Site Temporary Informational Signage				
2006-02	2/27/2007	Implementation of the Auto Shops Program in the City of Boston		D 00000 10	CBC 9-9.9	
2006-01	12/4/2006	Standard Rules and Procedures for Issue, Use and Care of ISD Equipment		Replaces CB 2002-18		
2005-03	0/4/0005	Policies and Procedures for Making Entry to an Occupied Residential		Incorporatos	2005 Federal Consent Decree	
2005-02	2/1/2005	Dwelling for Purposes of an Administrative Inspection		Incorporates, supercedes and revokes CB 1999-05	Sang Vo et. al. v. City of Boston (C.A. No. 00-11733-RWZ)	
2005-01	3/1/2005	ISD Personnel Authorized in Their Professional Capacity to Translate for ISD Customers/Constituents in Languages Other than English		1000 00	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
2004-01	3/15/2004	Establishing Procedure for Insurance Claim Notices of Loss Under G.L. c. 139 sec 3B			MGL c.139, s.3B	
0004.51	0/4.4/655.1	Boston Zoning Code Article 23 s.1; Off-street Parking Requirements with FAR				
2001-01	2/14/2001	of 6.0				Kevin Joyce
2001-02	4/5/2001	Special Operations Unit Established Guidelines for the Enforcement of the Site Cleanliness Ordinance in the City of				Kevin Joyce
2001-03	4/25/2001	Boston			CBC 9-9.8	Kevin Joyce

					1780 CMR 3310.1	
2001-04	6/14/2001	Required Permits for All Site Work			BZC Art. 8, Sect. 8-7	Kevin Joyce
2003-06	12/12/2003	Standard Fees for Certificates of Inspection (Annual and Temporary)			CBC 18-1.12	- term coyes
	12,12,2000	The state of the s			MGL c.40. s.22F	
2003-05	12/11/2003	Expansion of the Fast Track Program	Rescinded by CB2	Rescinds & replaces CB 1986-05	780 CMR 110.1	
2003-04	9/29/2003	Transfer of Building Documents to Off-Site City Archive Facility	Rescinded by CB 2011-05		CBC 9-1 MGL c.4. s.7	
2003-03**	9/29/2003	Guidelines for the Keeper of Records Responding to Requests for Records Made Under G.L. c.66 when the Exemption Enacted by c. 313 of the Acts of 2002 ("An Act Providing Protections Against Terrorism") as Codified in G.L. c.4, sec. 7(26)(n) (the "exemption clause") Pertaining to Non-Disclosure of Building Plans is Implicated			CB 2000-04 MGL c.4, s.7(26)(n)	
2003-03A	3/7/2003	Procedure for Off-Hours Inspection Requests and Third Party Billing	Rescinded byCB 2	Rescinds CB 2000-01		
2003-03	9/29/2003	Guidelines for the Keeper of Records Responding to Requests for Records Made Under GL c.66 ("Public Records Law") when the Exemption Enacted by c.313 of the Acts of 2002 ("An Act Providing Protections Against Terrorism") as Codified in GL c.4, s.7 (26)(n) (the "Exemption Clause") Pertaining to Non-Disclosure of Building Plans is Implicated				
2003-02A	8/1/2003	Standard Rules of Practice and Procedure for Field Services Division employees in regard to ISD's "Clean It or Lien It" program (not scanned)			CB 1993-03	Kevin Joyce
2003-02	8/1/2003	Implementation of the "Clean It or Lien It" program at Boston Inspectional Services				Kevin Joyce
2002-20	11/6/2002	Standard Rules and Procedures for Processing Permits and Licenses Issued by the Inspectional Services Department to Boards, Officers or Employees of the City of Boston Acting in their Official Capacity			CBC 18-5 CBC 18-7 c.222. Acts 1949	
2002-19	8/21/2002	Standard Rules for the Alternative Disposition of Legal Notices of Violation				
2002-18	7/29/2002	Standard Rules and Procedures for Issue, Use and Care of ISD Equipment				
	6/6/2002	Public Integrity Policy		Supplements CB 1999- 03		
2002-15	6/24/2002	Standard Rules and Procedures for the Embargo and Handling of Property				
2002-06f	10/16/2002	Standard Rules of Practice and Procedure for Weights and Measures Division (WMD) Personnel			CB 1993-03 CB 2002-17 CB 2002-02 CB 2002-02A CB 2002-18 CB 2002-04 CB 2002-15 MGL c. 6, s. 94-98, 101, 885 MGL c.98, s.29	
2002-06e	10/16/2002	Standard Rules and Proceudres for Housing Inspectors and Housing Inspection Division Employees			CB 1993-03 CB 1999-05 CB 2000-02 CB 2001-06	
2002-06d	10/18/2002	Republished version of CB 2002-01 pursuant to CB 2002-06	Į.			

2222 22	101101000	To:	1		IOD 0000 47
2002-06c	10/16/2002	Standard Rules and Proceudres for Health Division Personnel			CB 2002-17
					CB 2002-18
					CB 1999-03
					CB 1999-05
					CB 1999-06
					CB 2000-02
					CB 2002-02
					CB 2002-01
					CB 2002-15
					CBC 2-12.5
					105 CMR 410
					105 CMR 430
					105 CMR 590
					100 CIVIL COO
					MGL c.94, s. 146, 189A
					MGL c.111, s. 30, 122, 123, 125
					MGL c.114. s.49
2002-06b	1/15/2003	Standard Rules of Practice and Procedures for Environmental Services			CB 1987-04
		Inspectors and Employees			CB 1999-03
					CB 2002-02
					CB 2002-02A
					CB 2002-02A
					CB 2002-18
					CBC 9-9.8
					105 CMR 410
					105 CMR 590
					333 CMR 10
					780 CMR 119
					MGL c.132B
2002-06a	1/15/2003	Standard Rules of Practice and Procedure for Building, Electrical &			CB 2002-17
2002 000	1, 10,200	Mechanical Inspectors and Building & Structures Division Employees			CB 1999-05
		Woonanioa mopostoro ana Banang a Otrastares Bivision Employees			CB 2000-02
					CB 2001-06
2002-06	10/16/2002	Establishment of Standard Rules of Practice and Procedure for Field Division		Republished CB 2002-	(CD 2001-00)
2002 00	10/10/2002	Operations		01 as CB 2002-06d	
2002-05	5/23/2002	Time Standards for Processing Legal Notices of Violations of the State			MGL c.143
		Building Code			780 CMR
2002-04	5/9/2002	Inspectors, Code Enforcement Officers and ISD Personnel Assigned to			
		Department Motor Vehicles	<u> </u>	-	
2002-03	8/30/2002	Establishment of the On-Call Manager List and Standard Rules and	Rescinded by CB 2017-03		
2002 224	E/20/2000	Procedures for On-Call Managers Standard Dules of Procedure for Inspectional Comisses	CD 2017-03		MCL a 20A
2002-02A	5/20/2002	Standard Rules of Practice and Procedure for Inspectional Services Department Hearings			MGL c.30A
2002-02	5/20/2002	Designation of Inspectional Services Department Hearing Officer(s)			MGL c.31, s.41
2002-02	5/20/2002	Designation of inspectional octations Department Healing Officer(s)			MGL c.111, s.127B
					MGL c.143, s.9
1					Ch. 665, Acts 1956
<u> </u>	1	1		1	OII. 000, ACIS 1300

2002-01	7/30/2002	Standard Rules of Practice and Procedure for Housing Inspectors and	Republished as		CB 1993-03	
2002-01	1/30/2002	Housing Inspection Division Employees	CB 2002-06d by		105 CMR 410.820	
		Housing inspection Division Employees	CB 2002-00d by		CB 1999-05	
			CB 2002-00		CB 1999-05 CB 2000-02	
					CB 2000-02	
2000-09	10/23/2000	Haymarket Fish Vendor Dates of Operation			CR 2001-06	Kevin Joyce
2000-08	10/23/2000	Authorization of the Legal Division to Accept Service of Subpoenas,			Policy Statement 1992-01	Kevin Joyce
	10,20,200	Summonses and Legal Notices				
2000-07	10/20/2000	Porches and Decks: Design Affadavits			780 CMR 1	
2000-07	10/20/2000	Porches and Decks: Design Affidavits			780 CMR 16, 18, 23	Kevin Joyce
2000-06	5/23/2000	Boston Zoning Code Article 2 s.44 and Article 2A; Definition of "Street"			BZC Art. 2, s.44	Kevin Joyce
					BZC Art. 2A	
2000-05	5/1/2000	Interim Procedures for Issuing Building Permits for Work Requiring G-12	30 day interim			Kevin Joyce
		Licenses	, i			-
2000-04	3/29/2000	Administrative Procedure for Answering Request for Public Documents			MGL c.66, s.10	Kevin Joyce
2000-03	3/29/2000	Boston Zoning Code Article 2 s.24 Definition of Hotel			BZC Art. 2, s.24	Kevin Joyce
2000-02	2/24/2000	Modifying the Practice of Writing "Right of Entry" Violations			CB 1999-05	Kevin Joyce
2000-01	1/11/2000	Inspection Request and Payment for Off Hours				Kevin Joyce
2000-01	1/11/2000	Procedure for Off Hours Inspection Requests and Third Party Billing				Kevin Joyce
1999-07	9/15/1999	Definition and Requirements of an Affidavit Project in the City of Boston		Rescinds CB 1987-01	780 CMR	John Eade
1999-06	12/15/1999	Effective Warrant Management: The Collection of Information Relative to the				Kevin Joyce
		Identification of Responsible Parties for the Purpose of Executing and				
		Reducing the Backlog of Outstnading Housing Court Warrants				
1999-05	8/27/1999	Administrative Inspection Consent Forms				Kevin Joyce
1999-04	8/17/1999	Ethics Committee Established to Assist the Inspectional Services Department	Rescinded	Rescinded by CB2021-	MGL Ch. 268A	Kevin Joyce
		and Its Employees in Ensuring Strict Compliance with G.L. c.268A and G.L.		01	MGL Ch. 268B	
		c.268B				
1999-03	5/24/1999	Inspectional Services Department Employee Compliance with General Laws		Supercedes	MGL Ch. 268A	Gary Moccia
		Chapter 268A, the "State Ethics Law"		CB 1985-12		
1999-02	5/19/1999	Reconstruction of Buildings Under Article 4, Section 4-1 of the Boston Zoning		Replaces CB 1987-09	BZC Art. 4, Section 4-1	Gary Moccia
		Code			780 CMR	
1999-01	9/4/1998	Recession of Commissioner's Bulletins		Rescinds		John Eade
				CB 1987-03		
				CB 1987-04		
				CB 1987-05		
				CB 1987-09		
				CB 1994-03		
1000 01	= 100 1100=			CB 1996 01		ļ <u>-</u> .
1998-01	7/22/1997	Subdivisions Definition and Requirements of an Affidentit Project in the City of Restaur	D in to the OD (Danain de OD 4007 04	700 CMD	John Eade
1997-07	9/15/1998	Definition and Requirements of an Affidavit Project in the City of Boston	Rescinded by CB 2	Rescinds CB 1987-01	780 CMR	John Eade
1997-02	4/22/1997	Issuance and Enforcement of Sprinkler Permits	-		D7C A+ 96	John Eade John Eade
1997-01	10/7/1996	Removal of Structures Built Pursuant to Article 86 of the City of Boston Zoning Code			BZC Art. 86	John Eage
1996-01	2/15/1996	Testing/Approval of Sprinkler Permits	Rescinded byCB	1000 01	NFPA 13 - Ch. 8-1	John Eade
1995-01	4/3/1995	Demolition Delay	Rescinded byCB	1999-01	NEFA 13 - GII. 0-1	John Eade John Eade
1993-01	12/5/1994	Testing/Approval of Sprinkler Permits	Replaced by CB 1	QQ6_01	NFPA 13 - Ch. 8-1	John Eade
1994-01	8/8/1994	Issuing Interim Permits	Tropiaced by CD 1	000-01	N 1 A 10 - OII. 0-1	Garv Moccia
1994-01	9/22/1993	Expediting Certain Long Form Permit Applications	+			Thomas McNicholas?
1993-01	11/9/1992	Establishment of Maximum Allowable Occupant Loads in Places of Assembly	 		780 CMR 806.1	Thomas McNicholas?
1002-01	11/3/1992	(Applicable only to new assembly occupancies, or those seeking an increase in			248 CMR Sect. 2.10, Table 1	THOMAS WICHVICHOIDS!
		the existing capacity)			NFPA 101, Sect. 8-1.7.2 & 9-	
		THE EXISTING CAUACITYT	1	1	INCEA IOLOGGIO-L/Z&9-	

1989-01	2/8/1989	City of Boston Regulations for the Implementation of the Security Ordinance			CBC 9 (as amended by Ord.	Thomas McNicholas?
1969-01	2/0/1909					Thomas McNicholas?
		for Elderly/Handicapped Housing Developments			1984, c.26 and Ord. 1984, c.39)	
					MGL c.111, s.127A	
1988-06	7/6/1988	Existing Hazardous Materials			CBC Ord 1989 c 4	Thomas McNicholas?
1986-06 1987-11	11/6/1987	Chapter 354 - An Act Requiring Insurance Coverage for Plumbing and Gas			MGL c.142, s.21-21a	William Somers
1907-11	11/0/1907	Fitting Contractors			WGL C. 142, S.21-21a	William Somers
1987-10	10/20/1987	The Use of CPVC and Polybutylene Pipes for Wet Sprinkler Use		Rescinds and replaces	1985 NFPA 13 - Ch. 3-1.1.5	William Somers
1007 10	10/20/100/	The doc of or volaria raybatylene riped for vvol opininter doc		CB 1986-04	10001117110 011.0 111.0	Villiam Comorc
1987-09	9/22/1987	To Provide for the Restoration of Buildings Raised to their Foundation Under	Rescinded byCB	1999-01Replaced by CB	1BZC Art. 4, Sect. 4-1	William Somers
		an Order of the Commissioner of the Inspectional Services Department		, ,		
1987-08	9/3/1987	Modified Requirements for Certified Plot Plans				William Somers
1987-06	9/22/1987	Construction License Exemption Form for Homeowner(s)			780 CMR 109.1.1	William Somers
1987-05	8/31/1987	Requirements for Plan Submission and Microfilming Requirements	Rescinded byCB	1999-01		William Somers
		(Temporary)				
1987-04	5/14/1987	Rodent Extermination Requirements for Building Department Permit	Rescinded byCB	1999-01	105 CMR 410.550	William Somers
		Applications			780 CMR 108.6	
1987-03	4/29/1987	Regulations Governing the Resignation of the Servicing and Testing of	Rescinded byCB	1999-01	MGL c.98, s.34	William Somers
		Commercial Weighing and Measuring Devices			C.656, Acts 1965	
					CBC 1981 - Ch. 19	
1987-02	4/28/1987	Control for Ready Mix Concrete (Section 817.0 of the Massachusetts State		Rescinds		William Somers
		Building Code)		CB #179 (4/2/71)		
1987-01	1/16/1987	Definition of Requirements of An Affidavit Project in the City of Boston	Rescinded by CB		780 CMR 108.5	William Somers
				CB #180 (9/7/84)	780 CMR 108.6	
					780 CMR 127	
					CB 1986-06	
1986-06	12/15/1986	Calculation of Permit Fees, Definition of Fair Cost of Construction and		Replaces CB 1986-03	CBC Title 14, Section 450	William Somers
	10/10/1000	Application of Penalty Fees	5		01 1 01 1 0 1 100 0	
1986-05	12/10/1986	Fast Track Permitting Procedure for Commercial Office Buildings	Revised 4/4/88		State Bldg Code Sect. 108.6 CBC 1981 - Ch. 19	William Somers
1986-04	4/14/1986	The Use of CPVC Pipes for Wet Sprinkler Use	Replaced byCB 19	097 10	1985 NFPA 13 - Ch. 3-1.1.5	William Somers
1986-03	4/14/1986	Fair Cost of Construction - Permit Fees	Replaced by	967-10	Policy Statement 1986-06	William Somers
1000-00	4/14/1500	Tail Gost of Goristiaction - 1 Citille 1 CC3	CB 1986-06		l olicy ctatement 1900-00	William Comers
1986-02	4/14/1986	Legalization of Occupancy	05 1000 00			William Somers
1986-01	1/13/1986	Depositing Concrete in Cold Weather			State Bldg Code Sect. 108.6	William Somers
1985-01	9/25/1985	Construction of Basement Apartments			Art. 2, S.200 - State Bldg Code	William Somers
		'			780 CMR 802 - Art. 8, s.872	
					105 CMR 410.402	
					248 CMR Section 2 09(4)	
1984-01	9/7/1984	Application for a Permit- Affidavits				James Reid
1977-01	11/23/1977	Solid Fuel Burning Appliances				Francis Gens
		ABS and PVC Plastic Pipe, Schedule 40, for drainage, waste and vent			MA State Plumbing Code	
1972-04	10/13/1972	plumbing systems			Secs. 6.2.12 and 6.2.12.1	Robert Thuma Jr.
1972-03	8/28/1972	"Controlled Concrete" (Amended)	SupsedesCB #17	9		
1972-02	6/15/1972	Fire Protection for Monumental and Service Stairways	1		Standard 12 of BBC	Robert Thuma Jr.
1972-01	6/15/1972	Smoke & Heat Emergency Exhaust Systems				Robert Thuma Jr.
		Pland to beat the impression of the seals of registered professional Architects,	1			
		Structural Engineers,	1			
1971-03	5/3/1971	Mechanical Engineers, and Electrical Engineers				Robert Thuma Jr.
1971-01	4/2/1971	"Controlled Concrete"	Amended by CB #	‡179A		Robert Thuma Jr.
1969-01	2/28/1969	Operation of Passenger Elevators in case of Fire	ļ			Robert Thuma Jr.
1968-01	3/25/1968	Elevator, Dumb-waiter and Escalator Regulations			C.479, Acts 1938, Sec.116 (G)	Robert Thuma Jr.

			BBC, Part 26, Sec. 2601 and	
1967-04	5/2/1967	Ultimate Strength Design- Structural Analysis and Proportioning of Members	Sec. 116 (L)	Robert Thuma Jr.
			C.479, Acts 1938 as amended	
1967-03	4/10/1967	PYREX brand acid-waste drainline with Bury-Pac (TM) Casing	Sec.116 (L)	Robert Thuma Jr.
1967-02	3/20/1967	Dur-O-Wal Truss Design Joint Reinforcement in Masonry Walls		
		Watts # 8, 8A, 8C, and LF9 back-siphonage back-flow preventer. The #8 and		
		LF9 series preventers		
		are suitablefor hot and cold water service, inside or outside use. All working		
		parts are of stainless		
		steel. The device contains an atmospheric venting feature which allows water		
		to spill in the event		
		the water supply pressure becomes negative. The purpose of this device is to		
		prevent the flow of	C.479. Acts 1938 as amended	
1967-01	3/20/1967	contaminated or questionable water back into the potable water supply piping.	Sec.116 (L)	Robert Thuma Jr.
	0/20/1001		3333 (2)	Transfer Transfer Control
		Victaulic Couplings Style 31, 77, and 75 with housing fabricated in two or more		
		parts of malleable		
		iron castings in accordance with Federal Specifications QQ-I-666c, Grade II.		
		Coupling gasket shall		
		be Victaulic Grade "H" molded synthetic rubber, per ASTM-D735-61, Grade		
1005.01	4/00/4005	#R615BZ. Coupling bolts	C.479, Acts 1938 as amended	5 1 ()/ 1
1965-01	1/29/1965	shall be oval neck track head type with hexagonal nuts, per ASTM A-183-60. Bonding and Grounding System for Aluminum Sidings. (Lightning-Lok-	Sec.116 (L) C.479, Acts 1938 as amended	Robert York
1964-18	11/9/1964	Electrical Grounding System Electrical Grounding System	Sec.116 (L)	Robert York
1904-10	11/9/1904	Electrical Grounding System	Sec. 110 (L)	Robert fork
		Victaulic Couplings Style 31, 77, and 75 with housing fabricated in two or more		
		parts of malleable		
		iron castings in accordance with Federal Specifications QQ-I-666c, Grade II.		
		Coupling gasket shall		
		be Victaulic Grade "H" molded synthetic rubber, per ASTM-D735-61, Grade		
		#R615BZ. Coupling bolts	C.479, Acts 1938 as amended	
1964-17	10/26/1964	shall be oval neck track head type with hexagonal nuts, per ASTM A-183-60. Rescinded A nonbearing waii assembly consisting or 2 1/2 inch wide steel studs	Sec.116 (L)	Robert York
		supported at the top and		
		bottom with steel runners, faces both sides with 1/2 inch thick gypsum		
		wallboard, with the interior	C.479. Acts 1938 as amended	
1964-16	7/7/1964	,	Sec.116 (L)	Robert York
	1717.001	air space filled with mineral wool batts A noor and ceiling assembly composed of a concrete noor supported by steel	3333 (2)	T CONTROL TO THE
		cellular type floor		
		units, composed of upper and lower fluted section welded together to form full		
		cell sections, and		
		steel beams protected by sprayed fiber (Spraycraft) applied directly to the steel	C.479, Acts 1938 as amended	
1964-15	6/12/1964	surfaces	Sec.116 (L)	Robert York
		A structural steel building column protected by sprayed fiber ("Pyrospray")	C 470 Asta 4000 as amounded	
1004 44	C/4/40C4	applied directly to a	C.479, Acts 1938 as amended	Dahant Vanis
1964-14	6/1/1964	tamped depth of 2-3/4" A floor and ceiling assembly composed of a concrete floor supported by a	Sec.116 (L)	Robert York
		blend of cellular and		
		fluted-steel form units and a steel beam, protected by sprayed fiber		
		···· -······· -· -· -· -· -· -· , [- · - · - · · · · · · · · · · · · · ·		1
		("Pyrospray") applied directly	C.479, Acts 1938 as amended	

1		A floor and ceiling assembly composed of a concrete floor supported by a		
		blend of cellular and		
		fluted-steel form units and a steel beam, protected by sprayed fiber	C 470 Acts 1039 as amended	
1001 10	0/4/4004	("Pyrospray") applied directly	C.479, Acts 1938 as amended	Dalam Wala
1964-12	6/1/1964	to the steel surfaces A noor and centing assembly consisting of 2 172-inch thick cocrete topping on	Sec.116 (L)	Robert York
		cellular steel floor		
		units supported by a steel beam and protected by a suspended ceiling		
		consisting of 3/4" thick		
		acoustical tile (U.S.G Airson Acoustone "120") with light fixtures recessed into		
		boxes formed of	C.479. Acts 1938 as amended	
1964-11	6/1/1964	mineral wool batts	Sec.116 (L)	Robert York
1304-11	0/1/1904	Initiation wood batts	Sec. 110 (L)	Nobell Tolk
		A floor and ceiling assembly composed of a concrete floor supported by		
		combined cellular and fluted steel floor units (Fenestra) and a steel beam, and	C.479, Acts 1938 as amended	
1964-10	6/1/1964	, , , , , , , , , , , , , , , , , , , ,	Sec.116 (L)	Robert York
1004 10	0/1/1004	protected by sprayed fiber (Spraycraft) applied directly to the steel surfaces A noor and ceiling assembly composed of a concrete noor, a biend system of		TOBOR TORK
		fluted and cellular-steel		
		form units, trench header duct, and a steel beam, protected with a sprayed		
		fiber (Spraycraft) applied		
		directly to the undersurface of the form units and directly to the surfaces of the	C.479, Acts 1938 as amended	
1964-09	6/1/1964	beam	Sec.116 (L)	Robert York
	0, 1, 100 1	A structural steel column protected by sprayed fiber (Spraycraft) applied	333.1.0 (2)	- Control Control
		directly to the steel to a	C.479, Acts 1938 as amended	
1964-08	5/25/1964	tamped depth of 3 inches A noor and cening assembly composed or a 2 1/2-inch trick concrete topping	Sec.116 (L)	Robert York
		supported by a blend		
		system of fluted and cellular steel floor units (Inland Steel Products Co. "Hi		
		Bond,") and steel beams,		
		protected by sprayed fiber ("Spraycraft") applied, over a coating of adhesive,		
		directly to the exposed	C.479, Acts 1938 as amended	
1964-07	5/25/1964	surfaces, following the contours of the decking and beams	Sec.116 (L)	Robert York
		A structural steel column protected by sprayed fiber (Spraycraft) applied		
		directly to the steel to a	C.479, Acts 1938 as amended	
1964-06	5/25/1964	tamped depth of 2 inches	Sec.116 (L)	Robert York
		A floor and ceiling assembly composed of a 2 1/2" thick concrete topping		
		supported by cellular steel	2 4-2 4 4 422	
		floor unitsand steel beams protected by sprayed fiber applied directly to the	C.479, Acts 1938 as amended	
1964-05	5/22/1964	steel surfaces A noor and cening assembly composed or a z 1/z-inch trick concrete topping,	Sec.116 (L)	Robert York
		supported by cellular		
		steel floor units (Fenestra D deck) and steel beams, protected by sprayedfiber		
		(Spraycraft) applied		
		over a coating of adhesive directly to the exposed surfaces, following the		
		contours of the decking	C.479. Acts 1938 as amended	
1064.04	E/11/1064	and beams	-,	Dobort Vork
1964-04	5/11/1964	and beams A noor and ceiling assembly composed or a 2 1/2-inch trick concrete topping,	Sec.116 (L)	Robert York
		supported by cellular		
		steel floor units (Inland Steel Products) and steel beams employing a trench		
		header for electrical		
		wiring and protected by sprayed fiber (Spraycraft) applied over a coating of		
		adhesive directly to the	C.479. Acts 1938 as amended	
1964-03	5/11/1964	exposed surfaces, following the contours of the decking and beams	Sec.116 (L)	Robert York
1007-00	0/11/1004	perpendicular deliberation of the decking and beams	[000.110 (L)	I TODGET TOTA

1	1	A noor and ceiling assembly composed or a 2-1/2-inch thick concrete topping,		
		supported by a blend		
		of cellular and fluted steel floor units (Inlamd Steel Products) and steel beams,		
		protected by sprayed		
		fiber (Spraycraft) applied over a coating of adhesive directly to the exposed	0.470 Asta 4000 as assessed at	
4004.00	E/44/4004	surfaces, following the	C.479, Acts 1938 as amended	Dalam Wards
1964-02	5/11/1964	contours of the decking and beams	Sec.116 (L)	Robert York
		A lightweight precast tongue and groove 2" steel edge concrete a plank known		
		as Creteplank for use	C.479. Acts 1938 as amended	
1964-01	1/30/1964	in floor and roof decks as manufactured by the Martin Fireproofing Corporation	Sec.116 (L)	Robert York
	1,00,1001		C.479, Acts 1938 as amended	
1964	1/27/1964	Insulating Nailable Sheating (1/2" x 48" x 8'-0" or 9'0")	Sec.116 (L)	Robert York
		A floor and ceiling assembly consisting of a 2 1/2-inch thick concrete floor		
		supported by open-web steel joists protected with a 3/4-inch thick acoustical-	C.479, Acts 1938 as amended	
1963-27	10/11/1963	board ceiling	Sec.116 (L)	Robert York
		A floor and ceiling assembly consisting of a 2-inch thick concrete floor	` '	
		supported by open-web steel	C.479, Acts 1938 as amended	
1963-26	10/11/1963	joists protected with a 3/4-inch thick acoustical-board ceiling	Sec.116 (L)	Robert York
		A floor and ceiling assembly consisting of a 2-inch thick concrete floor		
		supported by open-web steel	C.479, Acts 1938 as amended	
1963-25	10/11/1963	joists protected with a 3/4-inch thick acoustical tile ceiling	Sec.116 (L)	Robert York
		A floor and ceiling assembly with concrete over steel form units with provisions		
		for electrical wiring	C.479, Acts 1938 as amended	
1963-23	8/9/1963	supported by steel beams and protected with perlite spray plaster A ricor and ceiling assembly consisting or a 2 3/4-inch thick concrete topping	Sec.116 (L)	Robert York
		on cellular steel floor		
		units, supported by steel beams and protected on the ceiling side with	0.470 Asta 4000 as amount to	
1000 00	0/0/4000	cementitous material.	C.479, Acts 1938 as amended	
1963-22	8/9/1963	(Gold Bond Fireshield spray plaster, Type F) A tioor and ceiling assembly consisting or a 2 1/2-inch thick concrete topping	Sec.116 (L)	Robert York
		on cellular steel floor		
		units, supported by steel beams and protected on the ceiling side with		
		cementitous material.	C.479, Acts 1938 as amended	
1963-21	8/9/1963		Sec.116 (L)	Robert York
1903-21	0/3/1303	(Gold Bond Fireshield spray plaster, Type F) A tioor and ceiling assembly composed or a concrete tioor supported by a	Sec. 110 (L)	ROBERTOIK
		blend of cellular and		
		fluted-steel form units and a steel beam protected by sprayed fiber applied		
		directly to the steel	C.479, Acts 1938 as amended	
1963-20	7/10/1963	surfaces	Sec.116 (L)	Robert York
		Tnemec No. 99 and Tnemec No. 69 primers used for the protection of	C.479, Acts 1938 as amended	
1963-19	7/10/1963	structural steel against rust	Sec.116 (L)	Robert York
		Ĭ Š	C.479, Acts 1938 as amended	
1963-18	7/2/1963	Glass pipe drainage systems used for conveying of corrosive wastes	Sec.116 (L)	Robert York
		A floor and ceiling assembly of a 2-inch thick concrete floor supported by open-	` '	
		web steel	C.479, Acts 1938 as amended	
1963-17	7/2/1963	joists, protected with a 3/4-inch thick (Acoustone "90") acoustical-tile ceiling	Sec.116 (L)	Robert York
		A floor and ceiling assembly of a 2 1/2-inch thick concrete floor supported by		
		open-web steel	C.479, Acts 1938 as amended	
1963-16	7/2/1963	joists, protected with 3/4-inch thick (Acoustone "120") acoustical-tile ceiling	Sec.116 (L)	Robert York

		A 4 1/2-inch thick, non load bearing partition constructed of 2 1/2-inch steel			
		studs with 3/8-inch			
		thick perforated rocklath screwed to the studs and 1/2-inch thick sanded			
		plaster (1:2 mix), on		C.479, Acts 1938 as amended	
1963-15	7/2/1963	each side		Sec.116 (L)	Robert York
		A floor and ceiling assembly consisting of 2 1/2" inch thick concrete floor			
		supported by open-web		C.479, Acts 1938 as amended	
1963-14	7/2/1963	steel bar joists protected by 5/8" thick labeled gypsum wallboard ceiling		Sec.116 (L)	Robert York
		An unprototed gypsum concrete rock deck, composed of bulb T-railst, 1/2-inch		<u> </u>	
		gypsum formboard		C.479, Acts 1938 as amended	
1963-13	7/2/1963	wire mesh reinforcement, and 2 1/2-inch gypsum concrete		Sec.116 (L)	Robert York
		U.S.G sheathing as manufacturing by the U.S Gypsum Co.		C.479, Acts 1938 as amended	
1963-12	7/2/1963	(1/2" x 24" x 8'-0' or 1/2" x 48" x 8'-0' or 9'0")		Sec.116 (L)	Robert York
		Cofar composite floor and roof construction as manufactured and engineered			
		by the Granco Steel		C.479, Acts 1938 as amended	
1963-11	5/22/1963	Product Company; Granite City, Illinois		Sec.116 (L)	Robert York
				C.479, Acts 1938 as amended	
1963-10	5/22/1963	Approval for use of Hi-Stress flexicore floor and roof slabs		Sec.116 (L)	Robert York
				C.479, Acts 1938 as amended	
1963-09	5/16/1963	Inland Hi-Brand (missing front page) A floor system composed or 2 1/2 inch thick, concrete topping over blend steel		Sec.116 (L)	Robert York
		floor units			
		112 -1 -111112			
		(cellular and fluted) supported by steel beams, with Gold Bond Fire-Shield Plaster spray applied			
		1 7 7		0.470	
4000 00	4/04/4000	directly on the exposed surfaces, following the contours of the decking and		C.479, Acts 1938 as amended	D 1 137 1
1963-03	1/24/1963	beams A noor system composed of 2 172 inch thick concrete topping on biend steel		Sec.116 (L)	Robert York
		floor units			
		(Holorib Deck & Elect- Re-form steel units) supported by steel beams with			
		Gold Bond Fire-			
		Shield Plaster sprayed directly on the exposed surfaces, following the contours			
		of the decking and		C.479. Acts 1938 as amended	
1963-02	1/24/1963	beams		Sec.116 (L)	Robert York
1303-02	1/24/1903	A floor system composed of 2 1/2 inch thick concrete topping on 3 inch ceilular		Sec. 110 (L)	ROBERTOR
		steel decking			
		supported by steel beams with Gold Bond Fire-Shield Plaster sprayed directly			
		on the exposed		C.479, Acts 1938 as amended	
1963-01	1/24/1963	· ·		Sec.116 (L)	Robert York
1000 01	172 17 1000	surfaces, following the contours of the decking and beams A 4 1/4 inch thick nonload-bearing Service Core wall partition constructed of 1		000.110 (2)	TODOR TOTAL
		inch thick "V"			
		Edge Gypsum Coreboard units spaced 1 1/8 inch apart and faced with 1/2			
		inch thick Sheetrock		C.479, Acts 1938 as amended	
1962-36	8/13/1962	gypsum wallboard panels		Sec.116 (L)	Robert York
		gypsum wallboard panels A floor and ceiling assembly consisting of a 2 1/2 inch thick concrete topping			
		on a 3 1/8 inch deep			
		cellular deck (composed of top units of 18 USS gauge and #16 USS gauge			
		bottom sheet) supported	Supersedes CB #52	C.479, Acts 1938 as amended	
1962-35	7/31/1962	by a steel beam	(Expired)	Sec.116 (L)	Robert York
		Steel beams protected with 7/8 inch and 5/8 inch "Sprayed 'Limpet' Asbestos"			
		fiber grade LW 25	Supersedes CB #52	C.479, Acts 1938 as amended	
1962-34	7/31/1962	applied to the steel surfaces (supporting a floor and ceiling assembly)	(Expired)	Sec.116 (L)	Robert York

		A moor and centry assembly consisting or a 2-5/0 mon trick, concrete topping		T	_
		on a blend system of			
		1 5/8 inch deep cellular and fluted decking (the cellular composed of 18 and 16			
		USS gauge top and			
		bottom respectively and the fluted 16 USS gauge) supported by a steel beam,			
		protected on the			
		underside with "Sprayed 'Limpet' Asbestos" fiber, Grade LW 25 applied	Supersedes CB #52	C.479. Acts 1938 as amended	
1962-33	7/31/1962	directly to the steel surfaces	(Expired)	Sec.116 (L)	Robert York
1902-33	7/31/1902	A 2 3/8 inch thick, nonload-bearing partition constructed of 1 inch solid	(Expired)	Sec. 110 (L)	Robert fork
		gypsum tongue and groove			
		core units faced on each side with 5/8 inch thick sheetrock firecode gypsum		C.479. Acts 1938 as amended	
1962-32	7/31/1962	board		Sec.116 (L)	Robert York
1002 02	770171002	A floor and ceiling assembly consisting of a 2 inch concrete floor supported by		CGC.110 (E)	TODEL TOIK
		open-web steel joist		C.479. Acts 1938 as amended	
1962-31	7/30/1962	protected by a 5/8 inch thick gypsum wallboard ceiling		Sec.116 (L)	Robert York
.002 0.	170071002	A 6 1/8 inch laminated nonload-bearing partition formed of two layers of		(2)	
		labelled 5/8 inch gypsum		C.479, Acts 1938 as amended	
1962-30	7/30/1962	wallboard on each face of steel studs		Sec.116 (L)	Robert York
		A Vaughan Movable Solid Sheetrock 2 1/4 inch nonload-bearing partition		, ,	
		constructed from 1 inch			
		solid gypsum core unts with 5/8 thick gypsum wallboard laminated to both		C.479, Acts 1938 as amended	
1962-29	7/27/1962	faces		Sec.116 (L)	Robert York
		A steel column protected with three layers of labelled 5/8 inch gypsum			
		wallboard having a total		C.479, Acts 1938 as amended	
1962-28	7/27/1962	thickness of 1 7/8 inches		Sec.116 (L)	Robert York
		A A 7/0 in the Abitaly resulted the action of the continuous and the c			
		A 4 7/8 inch thick nonload-bearing partition constructed of U.S Gypsum 3 5/8		0.470 Asta 4000 as amounted	
4000 07	7/07/4000	inch channel studs		C.479, Acts 1938 as amended	Daham Vanle
1962-27	7/27/1962	with 5/8 inch thick sheetrock Firecode wallboard, screw applied to both faces		Sec.116 (L) C.479, Acts 1938 as amended	Robert York
1962-26	8/17/1962	CADWELD method of butt splicing reinforcimg bars		Sec.116 (L)	Robert York
1902-20	0/1//1902	CADWELD Method of butt splicing reinforcing bars		C.479. Acts 1938 as amended	Robert Tork
1962-25	7/25/1962	CADWELD method of butt splicing reinforcimg bars		Sec.116 (L)	Robert York
1502-25	1720/1002	A 2 inch thick nonload-bearing Drywall partition constructed of 1 inch "V" edge		CCC.110 (E)	TODEL TOIK
		gypsum coreboard		C.479, Acts 1938 as amended	
1962-24	7/20/1962			Sec.116 (L)	Robert York
	172071002	units and faced with 1/2 inch thick Sheetrock Firecode wallboard panels A 5 3/4 inch thick nonload-bearing partition constructed of 3 1/4 inch Gold		(2)	
Ï		Bond nailable steel			
		studs spaced 24 inches on center faced with double thickness laminated 5/8			
		inch thick Gold Bond		C.479, Acts 1938 as amended	
1962-23	7/20/1962	fireshield wallboard applied to each face A 4 1/2 inch thick, nonload-bearing partition constructed of 3 1/4 inch Gold		Sec.116 (L)	Robert York
		· ·			
		Bond nailable steel			
		studs spaced 24 inches on center with 5/8 inch thick Gold Bond fireshield			
		wallboard applied to		C.479, Acts 1938 as amended	
1962-22	7/20/1962	each face		Sec.116 (L)	Robert York
		A 4 1/4 inch thick, nonload-bearing partition constructed of 3/8 inch thick Gold			
		Bond perforated			
		gypsum lath stapled to 2 1/2 Gold Bond nailable steel studs with 1/2 inch thick		0.470. Asta 4000 seems 1.1	
4000 01	7/00//000	sanded plaster		C.479, Acts 1938 as amended	D
1962-21	7/20/1962	(1:2 mix) applied to both faces		Sec.116 (L)	Robert York

		A 4 Inch thick, nonload-pearing partition constructed of 2 1/2 Inch Gold Bond		
		nailable steel studs		
		with metal lath nailed to the studs and 5/8 inch thick sanded plaster (1:2 mix)		
		measured from the	C.479, Acts 1938 as amended	
1962-20	7/20/1962	face of the lath	Sec.116 (L)	Robert York
		A 4 Inch thick, nonload-pearing partition constructed of 2 1/2 Inch Gold Bond	\ /	
		nailable steel studs		
		with metal lath stapled to the studs and 5/8 inch thick sanded plaster (1:2 mix)		
		measured from the	C.479, Acts 1938 as amended	
1962-19	7/20/1962	face of the lath	Sec.116 (L)	Robert York
		A 2 inch thick nonload-bearing partition constructed of 1/2 inch solid gypsum		
		plaster Baxbord core	C.479, Acts 1938 as amended	
1962-18	7/20/1962	units and faced on each side with 1/2 inch thick solid sheet rock A floor and ceiling assembly composed of a concrete floor supported by a	Sec.116 (L)	Robert York
		blend of cellular and		
		fluted-steel floor units and a steel beam, electrical header ducts, and junction		
		boxes protected by	C.479. Acts 1938 as amended	
1962-17	7/20/1962	a sprayed plaster	Sec.116 (L)	Robert York
1902-17	1120/1902	A floor and ceiling assembly composed of a biend system of ceilular and fluted-	Sec. 110 (L)	Robert fork
		steel form units,		
		electrical header ducts and junction boxes, reinforcing bars and concrete		
		topping protected with	C.479, Acts 1938 as amended	
1962-16	7/20/1962	vermiculite acoustical plaster or plaster	Sec.116 (L)	Robert York
		A floor and ceiling assembly composed of a concrete floor supported by a	(-)	
		blend of cellular and	C.479, Acts 1938 as amended	
1962-15	7/19/1962	fluted-steel floor units and a steel beam	Sec.116 (L)	Robert York
		A 4 1/4 inch thick, nonload bearing partition constructed of 3/8inch gold bond	, ,	
		plain gypsum lath		
		stapled to 2 1/2 inch Gold Bond nailable steel studs and 1/2 inch thick Perlite		
		plaster (1:2 mix)	C.479, Acts 1938 as amended	
1962-14	7/18/1962	applied to both faces	Sec.116 (L)	Robert York
		A 4 1/4 Inch thick, nonload bearing partition constructed or 3/8inch Gold Bond perforated gysum		
		lath nailed to 2 1/2 inch Gold Bond nailable steel studs and 1/2 inch thick		
		sanded plaster (1:2 mix)	C.479, Acts 1938 as amended	
1962-13	7/11/1962	applied to both faces	Sec.116 (L)	Robert York
1902-13	7/11/1962	applied to both races	C.479. Acts 1938 as amended	Robert York
1962-12	6/29/1962	Fire-resistive ratings	Sec.116 (L)	Robert York
1002-12	0/20/1002	A floor and ceiling assembly consisting of a 2 inch concrete floor supported by		TODOLL TOTA
		open-web steel joist	C.479. Acts 1938 as amended	
1962-11	7/2/1962		Sec.116 (L)	Robert York
	1.2.1002	protected with a 5/8 inch gypsum wallboard ceiling A 4 1/4 inch thick, nonload bearing partition constructed of 3/8inch gold bond	(-)	
		plain gypsum lath		
		nailed to 2 1/2 inch Gold Bond nailable steel studs and 1/2 inch thick Perlite		
		plaster (1:2 mix) applied	C.479, Acts 1938 as amended	
1962-10	7/2/1962	to both faces	Sec.116 (L)	Robert York
		A floor and ceiling assembly composed of a concrete floor supported by a		
		blend of cellular and	C.479, Acts 1938 as amended	
1962-09	6/28/1962	fluted-steel floor units and a steel beam	Sec.116 (L)	Robert York
		"Floor and Modified Beam Assembly"- A fire-retardant (Sprayed Limpet		
		Asbestos) protecting the	C.479, Acts 1938 as amended	
1962-08	6/1/1962	underside of steel deck floors and modified beams supporting them	Sec.116 (L)	Robert York

		5/8 inch Firecode 60 Sheetrock Wallboard as a ceiling for the fire protection of			
		wood joists floor		C.479, Acts 1938 as amended	
962-07	4/12/1962	construction		Sec.116 (L)	Robert York
702 0.	.,,			C.479, Acts 1938 as amended	T TO BOTT TO THE
962-06	4/11/1962	A fire-retardant incombustible acoustical tile 24"x48"x5/8' thick		Sec.116 (L)	Robert York
1002 00	17 1 17 1002	A THE FORM WHITE HIS CHARGE GOOD CONTROL THE TOTAL CONTROL THE CON		C.479, Acts 1938 as amended	T CODOLL TOTAL
962-05	4/11/1962	A fire-retardant incombustible acoustical tile 24"x48"x5/8' thick		Sec.116 (L)	Robert York
002 00	4/11/1002	"Asbestospray"- A fire-retardant material, composed of asbestos and other		000.110 (E)	TODOIT TOTA
		mineral fibers in proper		C.479. Acts 1938 as amended	
962-04	3/13/1962	proportions mixed with water and applied to metal surfaces		Sec.116 (L)	Robert York
JUZ-U T	3/13/130Z	"CAFRO-SPRAY" aka "Cafro Blaze-Shield," a fire retardant incombustible		GCC.110 (L)	TODGIT TOTA
		material used to fire-		C.479, Acts 1938 as amended	
962-03	3/7/1962	protect metal surfaces	Supercedes CB #72	Sec.116 (L)	Robert York
902-03	3/1/1902	Fanestra floor panel; floor system with floor panels and steel beams. Fire	Supercedes CB #12	Sec. 116 (L)	Robert fork
		protected by Cafco		C.479, Acts 1938 as amended	
060.00	0/00/4060	"Diaza Chield" plantared spiling			Debert Verle
962-02	2/23/1962	"Blaze-Shield" plastered ceiling SPRAYCRAFT- a fire-retardant, incombustible material, used to fire-protect		Sec.116 (L)	Robert York
	1	surfaces, and composed	Supercodes CP #60	C.479, Acts 1938 as amended	
060.04	1/10/1000		Supersedes CB #68		Robert York
962-01	1/12/1962	of mineral fibers, with asbestos	(5/17/1962)	Sec.116 (L)	
961-26	12/5/1961	"Glazon" (Prefaced Structural Masonary Units)-Lightweight Concrete		C.479, Acts 1938 as amended	Robert York
		Masonary units for interior bearing or nonbearing partitions		Sec.116 (L)	
961-25	11/15/1961R	ev "MonoKote" (MK-3)- a fire retardant, incombustible material used to fire protect	Supersedes CB #83	C.479, Acts 1938 as amended	Robert York
		metal surfaces and	(7/25/61)	Sec.116 (L)	
		composed of a proprietary cementitious mixture	,	` '	
961-24	10/30/1961	"Acousti-Celotex Protectone Striatone Plaid Natural Fissured"- an		C.479, Acts 1938 as amended	Robert York
		incombustible fire-retardant		Sec.116 (L)	
		acoustical tile 12" x 12" x 3/4" thick, with kerfed edges		· /	
961-23	10/18/1961	"Firecode"- a cementitious mixture for fire protection of metal surfaces. It may		C.479, Acts 1938 as amended	Robert York
		be either trowel-		Sec.116 (L)	
		applied or spray-applied to the metal surfaces. Trowel-Applied as a millmixed		(-)	
		plaster, it is			
		designated as Type "S" and when it is Spray-Applied the mixture is designated			
		as Type "D"			
961-22	10/4/1961	Armstrong Acoustical Fire Guard- an incombustible fire-retardant tile (24" x 48"		C.479. Acts 1938 as amended	Robert York
		by 5/8" thick)		Sec.116 (L)	T TO BOTH TO THE
961-21	8/31/1961	An incombustible fire-retardant acoustical tile nominally 24" x 48" and 24" x 24"		C.479, Acts 1938 as amended	Robert York
00121	0,01,1001	by 5/8" thick. The		Sec.116 (L)	TODOR TORK
		tile is either fissured or needle-perforated pattern		OCC. 110 (L)	
961-20	8/28/1961	"Lo-Tone Acoustical Tile" (12" x 12" x 5/8" thick)- an incombustible fire-		C.479, Acts 1938 as amended	Robert York
301-20	0/20/1901	retardant tile		Sec.116 (L)	NODELL TOLK
961-19	8/16/1961	A fire-retardant, acoustical tile 12" x 12" x 3/4" thick, with either kerfed edges		C.479, Acts 1938 as amended	Robert York
901-19	0/10/1901	and different pattern		Sec.116 (L)	Nobell Tolk
				Sec. 110 (L)	
		or kerfed edges and fissured pattern, or 12" x 12" x 5/8" thick tile with tongue			
	1	and grooves on two			
		sides amd kerfed edges on the other two sides, and with a small random hole			
	1	pattern, all three as			
061 40	8/4/1961	Gold Bond, Fire-Shiled Solitude Grid Panels (24" x 48" by 5/8" thick)- a fire		C.479, Acts 1938 as amended	Robert York
961-18	6/4/1961				KODER YORK
		retardant, incombustible		Sec.116 (L)	
		acoustical tile			

1961-17	7/25/1961	A Cementitious mixture designateed a Type 1, 2, and 3, mixed with water and	Rescinded by CB#91	C.479, Acts 1938 as amended	Robert York
		spray-applied directly		Sec.116 (L)	
		to the beams and to the under surface of the steel floor units. Type 2 and 3 will		, ,	
		be listed by the			
961-16	7/6/1961	Underwriters as is presently listed Type 1 material "Cementitious Mixture" Natco Vitrilite "Fireproofer" Facing Tile to be used in bearing and nonbearing		C.479, Acts 1938 as amended	Robert York
		walls and partitions		Sec.116 (L) and Sec.2407	
1961-15	7/17/1961	Approval of Copper Tubes and Pipes for use in Plumbing		C.479, Acts 1938 as amended	Robert York
		" "		Sec.116 (L)	
1961-14	6/28/1961	Armstrong Acoustical Fire Guard Lay in Units- a fire retardant, incombustible		C.479, Acts 1938 as amended	Robert York
		acoustical tile		Sec.116 (L)	
1961-13	6/29/1961	Armstrong Acoustical Fire Guard- a fire retardant, incombustible acoustical tile		C.479, Acts 1938 as amended	Robert York
		· ·		Sec.116 (L)	
1961-12	6/28/1961	Armstrong Acoustical Fire Guard- a fire retardant, incombustible acoustical tile		C.479, Acts 1938 as amended	Robert York
	0.20.1001			Sec.116 (L)	
1961-11	6/29/1961	Armstrong Acoustical Fire Guard- a fire retardant, incombustible acoustical tile		C.479, Acts 1938 as amended	Robert York
1001 11	0/20/1001	, in the state of		Sec.116 (L)	TODOR TORK
1961-10	6/29/1961	Armstrong Acoustical Fire Guard- a fire retardant, incombustible acoustical tile		C.479, Acts 1938 as amended	Robert York
1001110	3/20/1001	, interesting / reduction / in o order of the retaining interesting about the		Sec.116 (L)	TODOIL TOIK
1961-09	6/28/1961	Gold Bond Fire Shield Solitude Acoustical Tile- a fire retardant, incombustible		C.479, Acts 1938 as amended	Robert York
1001-00	0/20/1301	tile		Sec.116 (L)	ROBERT TORK
1961-08	6/23/1961	Gold Bond Fire Shield Solitude Acoustical Tile- a fire retardant, incombustible		C.479, Acts 1938 as amended	Robert York
1901-00	0/23/1901	tile		Sec.116 (L)	Nobell Tolk
1961-07	6/27/1961	Gold Bond Fire Shield Acoustiroc Acoustical Tile- a fire retardant.		C.479, Acts 1938 as amended	Robert York
1901-07	0/2//1901	incombustible tile		Sec.116 (L)	Robert Tork
1961-06	6/2/1961	"CAFCO-SPRAY" aka "Cafco Blaze-Shield"- a fire retardant incombustible	Rescinded by CB#95 (3/7/62)	C.479, Acts 1938 as amended	Robert York
1901-00	0/2/1901	material used to fire	Rescilided by CB#95 (3/1/02)	Sec.116 (L)	Robert Tork
				Sec. 116 (L)	
		protect metal surfaces and composed of a mixture of mineral wool asbestos			
1961-05	6/19/1961	"Master Column" - Concrete-filled columns		C.479. Acts 1938 as amended	Robert York
1001-00	0/13/1301	Waster Column Controle filled Columns		Sec.116 (L)	ROBERT TORK
1961-04	5/25/1961	Compacted Concrete Pile known as "Franki Pile"		C.479, Acts 1938 as amended	Robert York
1001-04	3/23/1301	Gornpacied Goriorete File Kriowit as Franki File		Sec.116 (L) and Sec.2908 of	RODGIT TOIR
				BBC	
1961-03	5/23/1961	Two hour Fire-Resistant Rating: 5/8" Gypsum Wallboard laminated in three		C.479, Acts 1938 as amended	Robert York
1001-00	3/23/1301	layers, total thickneess of 1-7/8"		Sec.116 (L)	ROBERT TORK
		layers, total tribkrieess of 1-770		3ec. 110 (L)	
1961-02	5/17/1961	"SPRAYCRAFT" - A Fire Retardant, Incombustible Material, used to fire-	Rescinded by CB#93	C.479, Acts 1938 as amended	Robert York
1901-02	3/11/1901	protect Metal Surfaces	Trescarded by CD#33	Sec.116 (L)	LYONGIT LOLK
1961-01	3/24/1961	"LO-TONE FR Mineral Acoustical Tile"- A Fire-Retardant, Incombustible	1	C.479, Acts 1938 as amended	Robert York
1001-01	3/24/1901	·		Sec.2201 & Sec.116, Paragraph	LYONGIT LOLK
		Ceiling Tile		(I)	
1960-07	10/25/1960	The Use of WRDA as a water-reducing admixture in structural concrete	+	(L)	Robert York
1960-07 1960-06	8/31/1960	The Use of WRDA as a water-reducing admixture in structural concrete The Use of Perlite Gypsum Plaster or Vermiculite Gypsum for Fireproofing	 	C.479. Acts 1938 as amended	Robert York Robert York
900-00	0/31/1900	Structural Steel			LODEIT TOLK
				Sec.116, Paragraph "L"	
1060.05	5/31/1960	Members in Buildings "PLACEWALL"- A liquid water reducing agent sold in two formulations.	+ +	C.479, Acts 1938 as amended	Robert York
1960-05	5/31/1960				KODER YORK
		Placewall-W; which entrains		Sec.116, Paragraph "L"	
1000 04	0/00/4000	air and Placewall-R: which entrains not over 1.5% air	+	0.470 A.t. 1000	D. b. at Vo. 1
1960-04	3/29/1960	Plain Porex Roof Slabs		C.479, Acts 1938 as amended	Robert York
1000 00	0/00//	NO 151 (111) 5 1/T 1 1/5 1/5 1/5	 	Sec.116, Paragraph "L" of BBC	D 1 ()/ (
1960-03	3/23/1960	Vinyl Plastic Lighting Panel (Trade name "Circlgrid")		C.479, Acts 1938 as amended	Robert York
				Sec.116, Paragraph "L" of BBC	

1960-02	2/1/1960	Tectum Roof Plank and Tectum Roof Tile		C.479, Acts 1938 as amended	Robert York
				Sec.116, Paragraph "L" of BBC	
1960-01	1/5/1960	"SPRAYCRAFT"- A Fire Retardant Sprayed Directly in the Underside of Steel		C.479, Acts 1938 as amended	Thomas Hughes
		Floors, Roofs, & on the		Sec.116, Paragraph "L" of BBC	
		Beams Supporting them			
959-13	10/29/1959	"HAYDITE" Expanded Shale Lightweight Aggregate for Concete use		C.479, Acts 1938 as amended	Thomas Hughes
				Sec.116, Paragraph "L" of BBC	· ·
959-12	9/28/1959	"PYRACOTE" Vermiculite Plaster, a factory-mixed, setting type plaster for		C.479, Acts 1938 as amended	Thomas Hughes
		trowel ot machine		Sec.116, Paragraph "L" of BBC	
		spray-on applications to steel surfaces			
959-11	9/17/1959	Double-Walled Insulated Metal Pipe Gas Vent, Type B-1	Supersedes CB	C.479, Acts 1938 as amended	Thomas Hughes
			#55 & #57	Sec.116, Paragraph "L" of BBC	
959-10		Missing	Rescinded by CB #58		
959-09	8/5/1959	"Strongbord" -Insulating Board Sheathing		C.479, Acts 1938 as amended	Thomas Hughes
				Sec.116, Paragraph "L" of BBC	
959-08		Missing	Rescinded by CB #58		
959-07	7/7/1959	"Waylite" (Lightweight Aggregate for Concrete use)		C.479, Acts 1938 as amended	Thomas Hughes
				Sec. 116, Paragraph "L"	
1959-06	5/26/1959	"Gold Bond Fire Shield Plaster" -A Fire-retardant Material Machine applied		C.479, Acts 1938 as amended	Thomas Hughes
		directly to the underside		Sec. 116, Paragraph "L" of BBC	
		of Metal Deck Floors. Roofs, and to the Steel Beams Supporting them			
959-05	5/21/1959	"Sprayed Limpet Asbestos"-A Fire-retardant Sprayed Directly on the under	Superseded by	C.479, Acts 1938 as amended	Thomas Hughes
		side of Steel Deck	CB #124, #125, & #126	Sec. 116, Paragraph "L" of BBC	
		Floors. Roofs. and on the Beams Supporting them			
959-04	5/1/1959	Insulrock Slabs on Roof Decks and Insulrock Nonbearing Fireproof Partitions		C.479, Acts 1938 as amended	Robert York
				Sec. 116, Paragraph "L" of BBC	
959-03	3/2/1959	Copper Tubing for Water Supply Systems		C.479, Acts 1938 as amended	Thomas Hughes
				Sec.116 (G)	
959-02	2/10/1959	Norlite Aggregate		C.479, Acts 1938 as amended	Thomas Hughes
				Sec. 116, Paragraph "L"	
959-01	1/6/1959RI: 1	1 Approval for Flexicore Floor and Roof Slabs as developed by the Flexicore		C.479, Acts 1938 as amended	Robert York
		Company Inc.		Sec.116, Paragraph "L" of BBC	
958-08	12/1/1958	Tufcor for use in Roof Construction		C.479, Acts 1938 as amended	Thomas Hughes
				Sec. 116, Paragraph "L"	
958-07	9/26/1958	Cofar for use in Reinfored Concrete Floor & Roof Construction		C.479, Acts 1938 as amended	Thomas Hughes
				Sec. 116, Paragraph "L"	
958-06	12/31/1958	Addendum to Bulletin #44: Added a manufacturer to approved steel cellular		C.479, Acts 1938 as amended	Thomas Hughes
		panels approved with		Sec. 116, Paragraph "L"	
		the same conditions & provisos			
958-05	6/5/1958	Authorization of Steel Cellular Panels & Sections for floors & Roofs as		C.479, Acts 1938 as amended	Thomas Hughes
		manufactured and		Sec. 116, Paragraph "L" of BBC	
		engineered by six (6) manufacturers Should they be listed?			
958-04	5/1/1958	Zonolite brand Vermiculite is an insulating fireproof mineral form of mica used		C.479, Acts 1938 as amended	Thomas Hughes
		a an ingredient in		Sec. 116, Paragraph "L" of BBC	
		a spray for fireproofing ceilings, by applying spray directly to metal			
958-03	5/1/1958	CAFCO Spray: A Fire Retardant Sprayed Directly on the Underside of Steel		C.479, Acts 1938 as amended	Thomas Hughes
		Floors, Roofs, & Beams		Sec. 116, Paragraph "L" of BBC	
	1	Supporting them			
958-02	4/8/1958	Rockwell Tamperproof Gas Cock		C. 479, Acts 1938 as amended	Thomas Hughes
				Sec. 116 (G) and 116 (L)	
958-01	4/7/1958	Fesco Board Roof Insulation		C. 479, Acts 1938 as amended	Thomas Hughes
				Sec. 116 (L) of BBC	
957-02	3/22/1957	Lightweight Sectional Masonry Chimney Van Packer Corporation		C.479, Acts 1938 as amended	Thomas Hughes
				Sec. 116, Paragraph "L" of BBC	

1957-01				
956-02	8/17/1956		C. 479, Acts 1938 as amended	Charles Callanan
		Lawson Pre-Cast Concrete Plank	Sec. 116. Paragraph "L"	
956-01	10/8/1956	Milcor Celluflor and Milcor Steel Roof Deck	C.479, Acts 1938 as amended	Charles Callanan
			Sec. 116, Paragraph "L"	
955-02	1/6/1955	Partition Assembly, Non-Bearning USG TRUSSTEEL Stud.	C.479, Acts 1938	John Mahoney
			Boston Building Code Sect.	1
			116(L)	
			Boston Building Code Sect.	
			2201(h)	
955-01	1/6/1955	Partition Assembly, Non-Bearing PYROBAR and Plaster	C.479, Acts 1938	John Mahoney
			Boston Building Code Sect.	
			116(L)	
			Boston Building Code Sect.	
			2201/b)	
951-01	4/16/1951	KILNOISE Acoustical Plaster		
950-05	12/7/1950	Concrete Filled Columns	Boston Building Code Sect.	John Mahoney
	1		116(L)	
1950-04	10/19/1950	Super-Sico Structural Insulation	Boston Building Code Sect.	John Mahoney
			116(L)	
950-03	10/19/1950	Durisol Soffit Blocks	Boston Building Code Sect.	John Mahoney
			116(L)	•
950-02	10/19/1950	Weldwood Composite Fire Door (Kaylo Core)	Boston Building Code Sect.	John Mahoney
			116(L)	•
950-01	6/23/1950	Vitroliner Prefabricated Flue, Type "E"	CB1946-05 / CB05	John Mahoney
949-06	12/19/1949	2" Solid Rocklath and Plaster Partition	C.479, Acts 1938	John Mahoney
1949-05	8/25/1949	Kaylo Insulating Roof Tile	C.479, Acts 1938	John Mahoney
949-04		Missing		
949-03		Missing		
949-02	8/25/1949	Larson Pre-Formed Waterproofing Units	C.479, Acts 1938	John Mahoney
949-01	5/20/1949	Approval of the Use of LELITE Lightweight Aggregate	C.479, Acts 1938	John Mahoney
948-03	12/30/1948	Approval of the Use of Cantilite Concrete Plank	C.479, Acts 1938	John Mahoney
948-02	6/4/1948	Approval of the Use of Met-Cro Steel Cross Bridging	C.479, Acts 1938	John Mahoney
			Boston Building Code Sect.	
			2506(e)	
948-01	5/26/1948	Approval for the Use of Fenestra Type "D" Building Panels	C.479, Acts 1938	John Mahoney
			Boston Building Code Sect. 28	
947-02	11/7/1947	Cinder Concrete Building Units Manufactured by the Concrete Masonry Units	C.479, Acts 1938	John Mahoney
		Company		
947-01	11/7/1947	Concrete Building UNits Manufactured by the Concrete Masonry Units	C.479, Acts 1938	John Mahoney
		Company		
946-07	10/16/1946	Approval of Concrete Plank	C.479, Acts 1938	John Mahoney
946-06	10/15/1946	Concrete Units Manufactured by the Concrete Products Company	C.479, Acts 1938	John Mahoney
946-05	9/5/1946	Concrete Units Manufactured by the Newton Brick & Cement Company	C.479, Acts 1938	John Mahoney
946-04	9/5/1946	Approval of Channelcrete Roof Slabs	C.479, Acts 1938	John Mahoney
946-03	8/23/1946	Approval of Clapseal	C.479, Acts 1938	John Mahoney
946-01	4/24/1946	Approval of Fire-Resistive Ratings	C.479, Acts 1938	John Mahoney
004.04	0/4.4/0004	Boston Zoning Code Article 23 s.1; Off-street Parking Requirements with FAR		
001-01	2/14/2001	of 6.0		Kevin Joyce
001-02	4/5/2001	Special Operations Unit Established		Kevin Joyce
.004.00	1/05/0001	Guidelines for the Enforcement of the Site Cleanliness Ordinance in the City of		
2001-03	4/25/2001	Boston	CBC 9-9.8	Kevin Joyce
	0/4.4/0004		780 CMR 3310.1	
2001-04	6/14/2001	Required Permits for All Site Work	BZC Art. 8, Sect. 8-7	Kevin Joyce

Commissioners Bulletins

2001-05		
2001-06		
2001-07		
2001-08		
2001-09		
2001-10		
2001-11		
2001-11A		
2001-12		
2001-13		
2001-14		
2001-15		
2001-16		
2001-17		
2001-18		
2001-19		