

Left – Front of 2 Milford – proposed to replace 4 windows - basement and 1st floor.

Right – 2 Milford with old windows and abutting building 1 Bond with replacements installed



Close up of 2 Milford outside and 1 Bond adjacent
Left side – left window is Milford, right is Bond



Window 1 – living Room



Window 2 living Room



Window 3 dining room – the right window is nailed shut because it is so broken, it won't stay closed.



Window 4 Dining room facing alley



Window 5 kitchen – facing alley



Window 6 Basement Hall – facing alley



Bedroom 1 – small windows facing street



Bedroom 2 – facing alley/back porch

