


**DESIGN REVIEW HEARING APP # 21.0890 FPC / 46 FARNSWORTH STREET**



Rendering  
Main Entrance




Actual Progress  
Main Entrance

Current Condition  
Our Entrance



Current Condition  
Our Entrance





Sketch

We are hoping to improve our entrance at 46 Farnsworth to match the finish of the noted assembly at #44 Farnsworth, which is the main entrance to the building.

- Paint the frame, stiles, and rails to match the new black hollow metal assembly at 44 Farnsworth (perhaps electrostatically or pre-catalyzed epoxy paint)
- Remove the solid material in the transom (all three)
- Provide new transom glass (one preferred, but three would be acceptable) in the transom
- Replace the brass door pulls with brushed chrome
- Replace the brass push bars with brushed chrome
- Replace the deadbolt with brushed chrome