123 Charles St

PRESENTATION TO BEACON HILL ARCHITECTURAL COMMISSION

123 FRANKLIN ST HISTORY

Inventory No:

BOS.14570

Historic Name:

Adams, Paul House

Common Name:

Burnce, Michael - Leavitt, J. W. Building

Address:

123 Charles St

City/Town:

Boston

Village/Neighborhood:

Beacon Hill; North Slope

Local No:

Year Constructed:

c 1845

Architect(s):

Architectural Style(s):

Altered beyond recognition; Classical Revival; Greek

Revival

Doctor Or Dentist Office; Hardware Store; Multiple Family

Dwelling House; Other Commercial; Single Family

Dwelling House

Significance:

Architecture; Commerce; Health Medicine

Area(s):

Use(s):

BOS.BE: Beacon Hill Historic District BOS.BY: Beacon Hill Historic District

Designation(s):

Local Historic District (12/02/1955); Nat'l Register District

(10/15/1966); Nat'l Historic Landmark (10/15/1966)

Roof: Tar, Built-up


Building Materials(s):

Wall: Brick; Galvanized Iron; Limestone; Metal,

Undetermined; Stone, Cut

Foundation: Stone, Cut


Source: MCRIS



In 1900's - tenement facade was constructed in front of the main elevation of a three-and-one-half-story, red brick, gable-roofed, c. mid-1840s town house.

Previous Demolition

- Removed metal roll up grilles
- Removed air conditioning unit




123 Charles façade before metal grilles' removal last month

EXISTING CONDITIONs – 123 Charles St' facade




EXISTING CONDITIONs – 123 Charles St' facade









Examples of existing entry door transoms – Neighborhood Around 123 Charles St







SCOPE OF WORK FOR 123 Charles St' FACADE

SCOPE:

- 1 Transom window-Remove existing ¼" clear plate glass infills and damaged mullions and replace with ¼" single-pane, clear safety glass 32" x 43" to match neighborhood examples.
- 2 In-kind repair gaps and scrape damaged exterior wood storefront as needed.
- 3 Remove all damaged plywood panels below windows and replace with exterior—grade MDO.
- 4 Paint all exterior wood storefront, with exterior-grade paint semi-gloss black.
- 5 Scrape and Paint existing door with exterior-grade paint semi-gloss black (alt dark green).
- 6 New wrought-iron (bracket) and wooden (signage). Location to match original placement.




123 Charles' façade – Existing Conditions


Materials and Specifications



- •1/4" Clear Tempered CAT II Impact-Rated (Safety Glass)
- •Heat-treated clear safety glass that breaks into small particles Glass Approvals: ANSI Z97.1, Class A; and CPSC 16 CFR 1201 Category II. by Oasis Specialty Glass



Abatron LiquidWood and WoodEpox Wood Restoration Kit Item no.1829944 | WRK60R




Benjamin Moore ben Exterior Paint- Low Lustre Low Lustre (542)

•Cleanup: Soap and Water •Resin Type: 100% Acrylic Latex •Recommended Use: Exterior

•MPI Rating: 15 •VOC Level: 45.0




Sanded 3/8 in. x 4 ft. x 8 ft. Douglas Fir 4-ply MDO P1s. It has weather-resistant resin overlay bonded to the wood by heat and pressure.



Balsam 567

Alternate door Paint



Universal Black 2118-10

Color for all

123 Charles St - Signage Shop Drawings

