## South End landmarks Commission


Design Review Hearing

10 Rutland Square

July 05, 2022

## **Proposed Project**

- Replace existing window wells with new egress window window wells to match those at 8 Rutland Square (attached mirror of 10 Rutland Square)
- Remove existing awning windows, drop sills for new wood double hung windows sized for code compliant egress
- Cap window wells with matching granite capstones and provide a white stucco finish on the inside of the window wells




**Existing Condition** 




Existing Condition of front garden




Close up view of garden



Existing window well



Existing window well at 8 Rutland Square




Existing window well at 8 Rutland Square










**Existing Enlarged Elevation** 

Proposed Enlarged Elevation



Section through Proposed Window Well

