

Tiago Pereira

RB Farina Roofing

Jan 15, 2026 | 20 Photos




Roof Repair and Chimney Repair Photo Report

Section 1

Farina will repair the selected slate roof area / Remove some of the non-working chimney crown bricks.

1




2



3




4



5



6



7




8



9



10



11




12



13



14



15



16



17



18



19



20

