
Lack of Crosswalks
Sidewalks not ADA Compliant
Lack of Bicycle Facilities
Mature Street Trees
On-Street Parking: 41 Spaces
Parking Restrictions:


Tremont to Cabot (S): 1 Hour Parking Raynor to Raynor: Resident Only







OPTION 1

Better Crossing at Tremont Street
Raised Crossing at Raynor Circle
Accessible Sidewalks and Crosswalks
Curb Extensions
Protected Bike Lanes
Bus Stop
Tree Loss (ADA Improvements): 6
Parking Loss: 25



Parking Remaining:





OPTION 2


Wider Sidewalk on North Side

Better Crossing at Tremont Street
Raised Crossing at Raynor Circle
Accessible Sidewalks and Crosswalks
Curb Extensions
Protected Bike Lanes
Bus Stop
Tree Loss (ADA Improvements): 1
Parking Loss: 36

Tree to be removed


Parking Remaining:





















City Of Boston

Martin J. Walsh, Mayor



Lack of Crosswalks
Sidewalks in Poor Condition
Lack of Bicycle Accommodations
Mature Street Trees
On-Street Parking: 43 Spaces
Parking Restrictions:

Raynor to Kerr: Resident Only -1 Hour Kerr to Dewitt: Resident Only

Cabot to Dewitt: Resident Only -1 Hour

OPTION 1

Raised Intersection at Dewitt
Raised Crossings at Raynor Circle and
Kerr Way
Accessible Sidewalks and Crosswalks
Curb Extensions at All Intersections
Protected Bike Lanes
Bus Stop

Parking Loss:

Parking Remaining:

OPTION 2

Remove Bus Stop

All of the Above

OPTION 3

Wider Sidewalk along Park

Raised Crossings at Raynor Circle and Kerr Way


Accessible Sidewalks and Crosswalks
Curb Extensions at All Intersections
Protected Bike Lanes


Bus Stop


Parking Loss:














Parking Remaining:















City Of Boston

Martin J. Walsh, Mayor




Sidewalks in Poor Condition

Lack of Bicycle Accommodations

Bus Stop

On-Street Parking: 21 Spaces








OPTION 1

Dewitt Drive

Accessible Sidewalks and Crosswalks
Curb Extensions at Shawmut Ave.
Buffered Bike Lane (WB)
Shared Lane (EB)
Bus Stop
Parking Loss: 13*
Parking Remaining: 8
*Some parking can be replaced on





















Two-way Traffic
Sidewalks not ADA Compliant
Lack of Bicycle Accommodations
Mature Street Trees
On-Street Parking: 17 Spaces





OPTION 1

One-Way Traffic

Accessible Sidewalks and Crosswalks

Buffered Bike Lanes

Bike Box


Tree Loss (ADA):

Parking Loss:

Parking Remaining:

Tree to be Removed





OPTION 2

Two-Way Traffic

Accessible Sidewalks and Crosswalks

Curb Extensions at All Intersections

Bike Lane (WB)

Shared Lane (EB)
Bike Box

Tree Loss (ADA): 7

Parking Loss: 17

Parking Remaining: 0

Tree to be Removed

